



PARTS DESCRIPTION:

TL022C LOW POWER DUAL OPAMP; (TEXAS INSTRUMENTS)
 MN3101 CLOCK GENERATOR FOR BUCKET BRIGADE DEVICE / BBD
 MN3007 AUDIO SIGNAL DELAY, 1024 STAGE LOW NOISE BBD
 (9-12-51.2 msec delay)
 CD4007 DUAL COMPLEMENTARY PAIR WITH INVERTER; (RCA)
 MN3101/MN3007 MANF PANASONIC; THESE ARE EQUIVALENT
 TO EC61639/EC61641 RESPECTFULLY.

Title	DOD FX75 FLANGER (10-15-84)
Size	Document Number
REV	B
	DRAWN BY: FABIAN P. HARTERY
	Date: November 20, 1994
	ISheet 1 of 1

A COMMON POINT (OR JUNCTION) IS ILLUSTRATED BY >> WHEN THIS IS NOT SEEN, WIRES WHICH CROSS OVER EACH OTHER ON THIS SCHEMATIC ARE "NOT" CONNECTED.

U6 CD4007 (3A, 2A, 1A, 1B, 1B) - MOMENTARY SWITCH USED TO ENGAGE EFFECT